

TO THE POINT ABOUT HOT WORK AND WELDING SAFETY

Review Quiz

Name _____ Date _____

Please provide answers to the following to show how well you understand the information presented during this program.

1. Infrared radiation (IR) safety glasses do not protect your eyes from direct exposure to the harmful light of a welding arc.
 - a. True
 - b. False

2. Most welding gloves are designed for directly holding extremely hot materials.
 - a. True
 - b. False

3. Powered air-purifying respirators and supplied-air respirators have an assigned protection factor of _____.
 - a. 10
 - b. 25
 - c. 50

4. A hot work permit is required for work performed in both designated and non-designated hot work areas.
 - a. True
 - b. False

5. The person who issues the hot work permit must verify all precautionary measures have been taken before signing the permit and allowing work to begin.
 - a. True
 - b. False

6. A fire watch should continue observing the work zone for _____ minutes after the hot work is completed.
 - a. 10
 - b. 20
 - c. 30

7. You should only have on hand the work materials you need to complete an immediate hot work task.
 - a. True
 - b. False

8. A pre-job inspection of tools, tanks, hoses and cables should only be conducted if there are indications that any of the equipment wasn't in good working order during a previous hot work operation.
 - a. True
 - b. False

9. You should utilize welding screens or curtains when nearby workers could be exposed to sparks and harmful light.
 - a. True
 - b. False

ANSWERS TO THE REVIEW QUESTIONS

1. a

2. b

3. b

4. b

5. a

6. c

7. a

8. b

9. a